

envirosuite FS Form-003 2250 Based NMT PM Report

1	C:ItO	Inform	12tiAi

1.1 CMS Ticket	393507			1.2 Airport/Urban	Airport
1.3 Inspection	Annual			1.4 Location	Balcultry
1.5 Site Number	NMT05			1.6 Date	08-Sep-21
1.7 Inspected by	Kial Wallace/	David Courtney			
1.8 Normal NMT Operation Interrupted		From	10:45	То	11:15

7. Occupational Health and Safety Check

Environmental exposure – Appropriate clothir	ng, wide brimmed hat	t, sunscreen, drinking fluids	Yes
Designated work are	ea – Use of witches h	nats, barricades as cordons	No
Personal Protective Equipment (PPE) – protective glo	oves, safety boots, hi	gh viz vest, insect repellent	Yes
Animal hazards	No	Traffic hazards	No
Height / door work	No	Work within 2M of edge	No
Ladder used	No	Harness used	No
Pole erected	No		
Multiple personnel required	Yes	Anchor points	No
Manual handling issues	Yes	Emergency equipment	No
Contact with electricity – Overhead power	No	Residual current devices	No
Structural earthing of buildings / installations	No	Risk of public injury	No
Working alone / isolated – means of communication	No	New hazards identified	No
Security or access issues	No		

Comments: Site Secure and no safety concern

11. Mechanical Inspection

i i incentament mopeetion					
Site Condition:		Good	✓		
Fence Condition:		Good	✓		
Cabinet Condition:		Good	✓		
Moisture Inside NMT:		None	✓		
Insect Infestation:		None	✓		
Windshield Foam:		Replaced	✓		
Bird Spike:		Good	✓		
Lightning Rod:		Good	✓		
Earth Connection:		Good	✓		
Pole and Pole Mounting Condition:		Good	✓		
Conduit Condition:		Good	✓		
Solar Panel Condition		Good			
Solar Battery Cabinet Condition:		Good			
Cleaned Solar Panel:		Yes			
Battery Terminal Check:		Yes	✓		
GPS Coordinates:	Altitude:	54m	Latitude: 53,414163	Longtitude:	-6,137969

40 Flootrical Imagestic

12. Electrical Inspection						
11.1 NMT LCD Display:	Good					
11.2 Door Switch:	Good					
1.11 NMT Model:	3639-A	1.9 NMT SNo:	3037367			
1.10 2250 SNo:	3007636	2250 Type:	G4 Light	11.5 Firmware Version:	4.5.0.92	
		Cal Report No:		Lab Certificate Date:		
Current Microphone Model:	4952	1.12 SNo:	3037367			
4.40 M T	0)//100			Г		
1.13 Modem Type:	GX400	Modem SNo:		IMEI Number:		

Pistonphone/ Calibrator Information

2.1 Pistonphone/Calibrator Mod	B&K Type 42	231 Calibrator			
2.1 Serial Number: 2460008		Cal Report No:	CDK2103317	2.2 Calibrated Date:	17/05/2021
2.5 Normalized Output (dB):	94,07			2.3 Atmos. Pressure (hPa)	
2.4 Atm			2.4 Atmos	. Pressure Correction (dB)	

Backup Battery Check:

Battery voltage with Load & Mains (13 to 14V at -10°C to 40°C): Battery voltage with load only, wait for 5 minutes before measuring (≥12V):

4			
1	2	3	4
13.24			
0.42			

Existing Microphone Calibration Acoustical Calibration:

Before Calibration

After Calibration

2.6 Expected Calibration Level (dB):	94	Calibrating Level (dB):	93,88
Sensitivity (mV/Pa):	30,61	New Sensitivity (mV/Pa):	30,3
Deviation from initial (dB):	-0,14	Deviation from last (dB):	-0,09
Deviation from last (dB):		Deviation from initial (dB):	0,05
()	-, -	CIC Calibration	
		CIC Reference Ratio (dB)	-36,7
		CIC Ratio (dB)	-36,7
		CIC Result	Passed
		<u> </u>	
2250 Replacement (New)	No		
2250 SNo:			
2250 Type:	Cal Report No :	Lab Certificate Date:	
		Firmware Version:	
13. Microphone Replacement (New)	No	-	
Microphone Model:	SNo:		
Acoustical Calibration:			
Before Calibration		After Calibration	
Expected Calibration Level (dB):		Calibrating Level (dB):	
Sensitivity (mV/Pa):		New Sensitivity (mV/Pa):	
Deviation from initial (dB):		Deviation from last (dB):	
Deviation from last (dB):		Deviation from initial (dB):	
		CIC Calibration:	
		CIC Reference Ratio (dB)	
		CIC Ratio (dB)	
		CIC Result	
	_		
18. Weather Station N/A	SNo:	Confirm weather data:	
		_	
Barix Instreamer		Confirm live data:	
19. Final Check Completed	Yes		
Any Other Comments:			
Need to replace battery, as voltage is very low.	Windshield replace	ed with new one.	

Call EMS B&K Operation Centre (EMS OC) on 1-866-583 0280 or +61 3 9508 4930 to verify NMT operation